



Photo 1. Aerial photo of the site.



Photo 2. Entrance to Tampa Fiberglass.



Photo 3. Fiberglass forms at Tampa Fiberglass.



Photo 4. Chemical drums at Tampa Fiberglass





Photo 5. Fence and warning sign at Chloride Metals, Inc.



Photo 6. Cover over stored soil at Chloride Metals, Inc.



Photo 7. View of Chloride Metals, Inc. from intersection of Yocam Diamond and Raleigh Streets.



Photo 8. Raleigh Street Dump entrance.





Photo 9. Vegetation on northern part of dump site.



Photo 10. Discards on northern part of dump site.





Photo 11. Dwellings on the northern part of the site.



Photo 12. Close-up of the dwellings.





Photo 13. Dwellings are constructed of castoff materials.



Photo 14. Outside sitting area; photographer also reported seeing a boat that they did not photograph.





Photo 15. Fire pit and chairs.



Photo 16. Makeshift chairs.





Photo 17. Small wetlands on the northern part of the site.



Photo 18. View southwest from wetlands in the utilities easement.