



**Photograph 1: On-site litter and trash**



**Photograph 2: On-site pond known as “the pool”**



**Photograph 3: One of the on-site brooks**



**Photograph 4: Hardened paint sludge**





**Photograph 5: On-site paint sludge and a drum lid**



**Photograph 6: Buried 55-gallons metal drum**



**Photograph 7: On-site area known as the “Sludge Hill”**



**Photograph 8: Area known as “Sludge Hill”**