Summary of Contaminant Source Areas and Data

Hadnot Point and Vicinity, Camp Lejeune, North Carolina

Robert E. Faye, P.E.

Robert E. Faye & Associates, Inc.



Summary of Available Pumpage Data

Type of Information	System/Component	Data Timeframe
Daily operations schedule	HP WTP individual supply wells	Nov 28, 1984– Feb 4, 1985
Hours pumped and corresponding pumping rates	HP and HB WTP individual supply wells	Oct 1988–Mar 1989
Total gallons pumped, average pumping rate, average daily withdrawal, and % of time inactive	HP and HB WTP individual supply wells	1993
Daily log for well pumps indicating operational status (on/off)	HP and HB WTP individual supply wells	Jan 1998–Jun 2008



Summary of Water Treatment Plant (WTP) Delivery Data

Type of Information	System/Component	Data Timeframe
Annual delivery rates	Hadnot Point (HP) WTP	1942–1998
Annual delivery rates	Holcomb Boulevard (HB) WTP	1975–1998
Monthly rates of raw water supplied/treated water delivered	HP and HB WTPs	Sep 1955–Jan 1957 Jan 1980–Dec 1984 Jan 1982–Dec 1993 Jan 1987–Feb 1989
Daily rates of raw water supplied/treated water delivered	HP and HB WTPs	Jan 1995–May 1999 Jan 2000–Dec 2005




Data Availability

Item	Hadnot Point and vicinity	Tarawa Terrace and vicinity
Active model domain	50 mi ²	2.1 mi ²
Wells and boreholes (including hydropunch)	868*	222
Water-level measurements	5,407*	789
Groundwater samples analyzed for chlorinated solvents (PCE, TCE, DCE, Vinyl Chloride)	2,420*	192
Groundwater samples analyzed for Benzene, Toluene, Ethylbenzene, and Xylenes (BTEX)	2,611*	191
Supply well tests	69 supply wells 132 pump/aquifer tests	15 supply wells [†] 19 pump/aquifer tests [†]
Monitor well tests	67 monitor wells 25 pump/aquifer tests 60 slug tests	14 monitor wells 14 pump/aquifer tests

^{*} Does not include data from over 100 reports that summarize underground storage tank (UST) and aboveground storage tank (AST) subsurface investigations.

Includes data from 6 Mont***PDnRsvApFvFils.SUBJECT TO CHANGE ***

Subsurface Investigation Sites




Landfill Area

Hadnot Point Industrial Area




Site 88

PCE Contamination in Groundwater






TCE Contamination in Groundwater







Benzene Contamination in Groundwater





PCE Contamination in Groundwater Section A-A'






*** D R


Easting coordinates, in feet (State Flage Coordinate System for North Carolina, NAD 1983 datum)


PCE Contamination in Groundwater Section A-A', Detections Only






TCE Contamination in Groundwater Section A-A'






Easting coordinates, in feet (State Plane Coordinate System for North Carolina, NAD 1983 datum)


TCE Contamination in Groundwater Section A-A', Detections Only






Benzene Contamination in Groundwater Section B-B'






Easting coordinates, in feet (State Plane Coordinate System for North Carolina, NAD 1983 datum)

Benzene Contamination in Groundwater Section B-B', Detections Only





Primary TCE and PCE plumes in groundwater



Questions?

